

# **MICHIGAN SOUTHERN RAILROAD CO.**

---

## **FREIGHT TARIFF MSO-9050**

**NAMING  
RULES AND CHARGES  
FOR  
INSPECTIONS  
APPLYING AT  
STATIONS ON THE  
MICHIGAN SOUTHERN RAILROAD CO.**

---

## **INSPECTION TARIFF**

---

**ISSUED: October 31, 2012**

**EFFECTIVE: November 1, 2012**

---

**Issued By:**

**Pioneer Railcorp Commercial Department  
Acting as Agent for Subscribing Carrier  
5619 DTC Parkway, Suite 650  
Greenwood Village, CO 80111**

**FREIGHT TARIFF MSO-9050**  
(CONTINUED)

---

**INSPECTION RULES AND CHARGES**

**THE FOLLOWING RULES AND CHARGES ARE APPLICABLE TO INSPECTIONS ON THE MICHIGAN SOUTHERN RAILROAD CO. (MSO)**

Any time any locomotive, track, bridge, culvert, signal, crossing protection device, or other railroad facility or fixture may have suffered damage due to the actions of a third party, MSO shall, as soon as is practical, perform a safety inspection of such property.

**Rates for such inspections are as follows:**

|  |           |
|--|-----------|
| Locomotive inspection                              | \$ 750.00 |
| Track Inspection                                   | 750.00    |
| Signal / Crossing Protection Device                | 750.00    |
| Bridge / Culvert / Trestle                         | 1,500.00  |
| Bridge requiring special equipment/personnel, etc. | 5,000.00  |
| Railcar  | 250.00    |
| Miscellaneous facility / fixture                   | 250.00    |

The above charges are to assess the extent of damage and need for repair/replacement of the track/facility/fixture. These charges do not cover the cost of such repair or replacement.

This Tariff issued under the authority of the Interstate Commerce Act, 49 U.S.C. Section 10702.

-END-

---