

RIPLEY & NEW ALBANY RAILROAD CO.

FREIGHT TARIFF RNA-9050

NAMING
RULES AND CHARGES
FOR
INSPECTIONS
APPLYING AT
STATIONS ON THE
RIPLEY & NEW ALBANY RAILROAD CO.

INSPECTION TARIFF

ISSUED: October 31, 2012

EFFECTIVE: November 1, 2012

Issued By:

**Pioneer Railcorp Commercial Department
Acting as Agent for Subscribing Carrier
5619 DTC Parkway, Suite 650
Greenwood Village, CO 80111**

FREIGHT TARIFF RNA-9050
(CONTINUED)

INSPECTION RULES AND CHARGES

THE FOLLOWING RULES AND CHARGES ARE APPLICABLE TO INSPECTIONS ON THE RIPLEY & NEW ALBANY RAILROAD CO. (RNA)

Any time any locomotive, track, bridge, culvert, signal, crossing protection device, or other railroad facility or fixture may have suffered damage due to the actions of a third party, RNA shall, as soon as is practical, perform a safety inspection of such property.

Rates for such inspections are as follows:

Locomotive inspection	\$ 750.00
Track Inspection	750.00
Signal / Crossing Protection Device	750.00
Bridge / Culvert / Trestle	1,500.00
Bridge requiring special equipment/personnel, etc.	5,000.00
Railcar	250.00
Miscellaneous facility / fixture	250.00

The above charges are to assess the extent of damage and need for repair/replacement of the track/facility/fixture. These charges do not cover the cost of such repair or replacement.

This Tariff issued under the authority of the Interstate Commerce Act, 49 U.S.C. Section 10702.

-END-
